## Physical Environment

Appendix 7C: Site Inspection Photographs

## **List of Photographs**

Photograph 01: Looking east along the B1348 Edinburgh Road towards the Application Sit	:e 1
Photograph 02 : Looking west towards the B1348 Edinburgh Road (Application Site to RHS	) 1
Photograph 03: Looking east at the retaining wall between the Application Site and the B	1348
Edinburgh Road	2
Photograph 04: The Application Site viewed from the B1348 Edinburgh Road	2
Photograph 05 : John Muir Way footpath, looking east	3
Photograph 06 : John Muir Way footpath – looking west	3

## **7C** Site Inspection Photographs



Photograph 01: Looking east along the B1348 Edinburgh Road towards the Application Site.



Photograph 02: Looking west towards the B1348 Edinburgh Road (Application Site to RHS)



Photograph 03 : Looking east at the retaining wall between the Application Site and the B1348 Edinburgh Road



Photograph 04 : The Application Site viewed from the B1348 Edinburgh Road



Photograph 05 : John Muir Way footpath, looking east



Photograph 06 : John Muir Way footpath – looking west



Photograph 07: Revetment and Seawall



Photograph 08 : West end of Seawall